



VEH Photo #49 - Right Side - Outboard Side of Tag-Axle Broken Disc Brake Carrier Housing (Source: Dallas County Sheriff's Dept.)